
Mass Airflow Sensor

Topic number	LI15.00-N-036227
Version	1
Design group	15.00 General
Date	09-27-2005
Validity	Sprinter MY02-06
Reason for change	

Complaint:

No throttle response

Cause:

MAF provides incorrect mass airflow value

Remedy:

Disconnecting the MAF makes the ECM using a default value.

If complaint is gone with the MAF disconnected, the MAF is defective and needs to be replaced.

Symptoms
Power generation / Engine management / Engine performance / Poor/delayed throttle response